



# County of Fairfax, Virginia

## ADDENDUM

DATE: February 20, 2015

### ADDENDUM NO. 1

TO: ALL PROSPECTIVE OFFERORS  
REFERENCE: IFB 2000001477  
TITLE: Underground Fuel Tanks Removal & Replacement  
DUE DATE/TIME: March 18, 2015 / 2:00 PM (**Revised**)

The referenced request for proposal is amended as follows:

1. The due date/time has been changed to March 18, 2015 / 2:00 P.M.
2. Due to the inclement weather this week, a 2<sup>nd</sup> pre-bid conference has been scheduled for February 25, 2015 at 9:00 A.M., in Suite 417 at the Fairfax County Government Center, 12000 Government Center Parkway, Fairfax VA 22035.
3. Refer to Attachment I for responses to the questions from the pre-bid conference held on February 18, 2015.

All other terms and conditions remain the same.

Kristy D. Apperson  
Contract Specialist II

**THIS ADDENDUM IS ACKNOWLEDGED AND IS CONSIDERED A PART OF THE SUBJECT INVITATION FOR BID:**

\_\_\_\_\_  
Name of Firm

\_\_\_\_\_  
(Signature)

\_\_\_\_\_  
(Date)

**A SIGNED COPY OF THIS ADDENDUM MUST BE INCLUDED IN THE BID OR RETURNED PRIOR TO DUE DATE.**

**Department of Purchasing & Supply Management**  
12000 Government Center Parkway, Suite 427  
Fairfax, VA 22035-0013

**Website:** [www.fairfaxcounty.gov/dpsm](http://www.fairfaxcounty.gov/dpsm)

**Phone** 703-324-3201, **TTY:** 1-800-828-1140, **Fax:** 703-324-3228

ATTACHMENT 1

- Q1. In your specification and scope of work, you state that offerors must "Provide and install five gallon double-walled overspill containment basin – 1per tank.", however in the Tank Specifications this overspill tank has a capacity of fifteen gallons. Which size does the county want installed?
- A1. That was an error on our part. The following paragraphs are modified to read as follows:
- i) Page 24 item #5- change fifteen (15) gallon spill bucket to five (5) gallon double walled spill bucket.
  - ii) Page 28, item #5, change from fifteen (15) gallon spill bucket to five (5) gallon double walled spill bucket.
  - iii) Page 33, item #5 - change from fifteen (15) gallon spill bucket five (5) gallon double walled spill bucket.
- Q2. At the Government Center site, there is mention of a water separator tank that needs to be replaced, how many parts per million discharge should the separator be rated at?
- A2. We are still looking into this and will provide an answer after the next pre-bid conference.
- Q3. Do you have drawings for any of the sites?
- A3. We have found drawings for the Government Center Site. A copy of the drawing is attached separately to the solicitation page. If you would like a hard copy please email the Contract Specialist and one can be provided to you.